

[Home](#) ■ [Solutions](#) ■ [Sewer and Stormwater](#)

HUBER Solutions for Sewer Systems

THERE ARE MANY PROBLEMS WITH SEWER SYSTEMS:

- A substantial portion of the collected sewage does not even arrive at a treatment plant. Particularly through combined sewer overflows (CSO), a substantial portion of the yearly freight is discharged directly into receiving waters. And usually it is not even known how much sewage and waste is discharged through CSOs.
- Floating and suspended matter are also directly discharged into receiving waters through storm tank overflows.
- Sediments in storm water tanks are often not removed and treated effectively and efficiently.
- Solids are deposited in sewers and inverts during dry weather flow, they begin to rot and cause odor and corrosion problems. During heavy storm events they are remobilized and overload wastewater treatment plants as a freight peak or are directly discharged into receiving waters through overflows.
- Sewage pumps in lifting and forwarding stations are often clogged by coarse solids.
- Essential components of sewer manholes are corroding.

We offer efficient and reliable HUBER Solutions for all these problems:

- [Sewers](#)
- [Storm Tanks](#)

Downloads

 [Overview brochure: HUBER Sewerage Program](#) [pdf, 2.67 MB]

Photos



Products

- [HUBER Multi-Rake Bar Screen RakeMax®](#)

- [Combined Sewage Screens - Screens for sewer overflows](#)
- [HUBER Coarse Screen TrashMax®](#)
- [Manhole Equipment](#)
- [HUBER Pumping Stations Screen ROTAMAT® RoK4](#)
- [HUBER Storm Screen ROTAMAT® RoK1 for stormwater discharges](#)
- [HUBER Storm Screen ROTAMAT® RoK2 for stormwater discharges](#)

Adresse / address: HUBER SE · Industriepark Erasbach A1 · 92334 Berching · Germany · Telefon / phone: + 49 - 84 62 - 201 - 0 · Fax / fax: + 49 - 84 62 - 201 - 810
e-mail: info@huber.de · Internet: <http://www.huber.de>

Sitz der Gesellschaft / Headquarters: Berching · AG Nürnberg / Register of companies: HRB 25558

Vorstand / Board: Georg Huber (Vorsitzender / CEO), Dr.-Ing. Oliver Rong (stellvertretender Vorsitzender / Vice CEO), Dr.-Ing. Johann Grienberger, Rainer Köhler
Aufsichtsratsvorsitzender / Chairman of the Supervisory Board: Alois Ponnath

USt (VAT)-IdNr.: DE 812353219

Bank: HypoVereinsbank Nürnberg (BLZ 760 200 70) 5 008 409 · SWIFT-BIC: HYVEDEMM460 · IBAN: DE 30 7602 0070 0005 0084 09

