

[Home](#) ■ [Products](#) ■ [Stainless Steel Equipment](#) ■ [Drinking Water Storage](#) ■ [Air Filtering](#)

[Aeration of water reservoirs](#)

Filtering the supply air reduces hygiene hazards

Every drinking water reservoir respirates: Aeration and deaeration of drinking water reservoirs is necessary for pressure equalisation as the water level in the water chamber varies. Huge amounts of air are sucked in as drinking water is being withdrawn. This air must be pressed out again during tank filling. The hygiene problem lies in the “breath-in” process. Depending on ambient air quality, there is a certain risk that higher amounts of dust, bacteria, viruses and germs may pass into the stored drinking water.

Ventilation technology with HUBER air filter plants reliably prevents such risks. Generally, only filtered ambient air should be allowed to pass into the water reservoir.

We will gladly advise you on the right filter technology and suitable complete solutions for optimal hygiene for your drinking water reservoir

[Aeration / deaeration plant L251](#)



Natural aeration/deaeration plant with air connections on both sides to improve the hygiene in drinking water reservoirs.

Completely made of 1.4307 stainless steel except the filter material, shielded arc welded, acid-treated in a pickling bath and passivated.

Maximum throughput at $\Delta p = 120 \text{ Pa}$: 250 m³/h.

[Aeration / deaeration plant L252](#)



Natural aeration/deaeration plant with air connections on both sides to improve the hygiene in drinking water reservoirs.

Completely made of 1.4307 stainless steel except the filter material, shielded arc welded, acid-treated in a pickling bath and passivated.

Maximum throughput at $\Delta p = 120 \text{ Pa}$: 300 m³/h

[Aeration / deaeration plant L361, L661, L662](#)

Natural aeration/deaeration plant with air connections on both sides to improve the hygiene in drinking water reservoirs. Completely made of 1.4307 stainless steel except the filter material, shielded arc welded, acid-treated in a pickling bath and passivated.

Maximum throughput at $\Delta p = 120 \text{ Pa}$: 720 m³/h (L361), 1440 m³/h (L661), 3.012 m³/h (L662)



Download Documents

Here you will find extensive planning documents and customer information.

For quick and easy download, all documents of a product are packed together into one complete ZIP file:

- [Aeration / deaeration plant L251](#)
- [Aeration / deaeration plant L252](#)
- [Aeration / deaeration plant L361](#)
- [Aeration / deaeration plant L661](#)

Media



HUBER air filter for drinking water storage tanks

Case Studies

- [Old installations – a ticking bomb?](#)
- [Good reasons to use air filters in water reservoirs](#)
- [Minimised condensation in water chambers through forced ventilation](#)
- [Stadtwerke Bielefeld continue to invest into HUBER products for the refurbishment of water reservoirs](#)
- [Water reservoir Talstraße renovated](#)
- [Water Reservoir Schönforst refurbished by HUBER](#)
- [Drinking Water Protection - Complete Refurbishment of a Pressure Increasing Plant Bredstedt](#)

More products of this group: Drinking Water Storage

- [Water Reservoir Access](#)

Adresse / address: HUBER SE · Industriepark Erasbach A1 · 92334 Berching · Germany · Telefon / phone: + 49 - 84 62 - 201 - 0 · Fax / fax: + 49 - 84 62 - 201 - 810
e-mail: info@huber.de · Internet: <http://www.huber.de>

Sitz der Gesellschaft / Headquarters: Berching · AG Nürnberg / Register of companies: HRB 25558
Vorstand / Board: Georg Huber (Vorsitzender / CEO), Dr.-Ing. Oliver Rong (stellvertretender Vorsitzender / Vice CEO), Dr.-Ing. Johann Grienberger, Rainer Köhler
Aufsichtsratsvorsitzender / Chairman of the Supervisory Board: Alois Ponnath

USt (VAT)-IdNr.: DE 812353219

Bank: HypoVereinsbank Nürnberg (BLZ 760 200 70) 5 008 409 · SWIFT-BIC: HYVEDEMM460 · IBAN: DE 30 7602 0070 0005 0084 09

